

Hello from Italy with my 280CE

Post by "Insulaner" of Mar 26th 2020, 9:10 pm

Hi Lucian,

found it. Was actually me that started this thread; had completely forgotten that fact 😊

[Bremssattel Schrauben](#)

Reason I asked was I would not have a good feeling changing everything on a brake calliper and leaving 40 to 50 year old O-Rings between the two halves. Although I have to admit I would not know any case where those failed.

Kind Regards,

Hagen

.