

M189 cylinder liner and head gasket questions.

Post by "Insulaner" of May 1st 2021, 9:00 am

Hi Ron,

[Quote from Ron B .](#)

That's a really good idea actually. And something I will definitely try.

when you take the cam wheel diameter and the height of the material taken off (0.9mm) you can calculate the correction angle of the key required. With those rip-off prices I would avoid trial and error.

Kind Regards,

Hagen

.